

201315

中国 上海市

浦东康桥工业区康柳路303号

上海特波电机有限公司

VP Engineering 或其他UL相關負責人



VP Engineering
 SHANGHAI TOP MOTOR CO LTD
 303 KANGLIU RD
 KANGQIAO INDUSTRIAL AREA
 NANHUI
 SHANGHAI
 201315 CHINA

Date: 2015/01/14
 Subscriber: 100029614
 PartySite: 566908
 File No: EX26635
 Project No: 4786519185
 PD No: 15M01706
 Type: R
 PO Number:

Subject: **Procedure And/Or Report Material**

The following material resulting from the investigation under the above numbers is enclosed.

Issue

<u>Date</u>	<u>Vol</u>	<u>Sec</u>	<u>Pages</u>	<u>Revised Date</u>
2014/12/31	1	1	Cert of Compliance	

Corrections to previously sent out project # 4786519185.

Inspections at your plant will be conducted under the supervision of SHARI ZHENG, UL INSPECTION CENTER SHANGHAI, NO 68 HUATUO RD, BLDG 9, ZHANGJIANG HI-TECK PARK, PUDONG NEW AREA, SHANGHAI, ., China, 201203., PHONE: 21-6364-6538, FAX: 21-3868-2860, EMAIL: SHIC@CCICSHANGHAI.COM

Please file revised pages and illustrations in place of material of like identity. New material should be filed in its proper numerical order.

NOTE: Follow-Up Service Procedure revisions DO NOT include Cover Pages, Test Records and Conclusion Pages. Report revisions DO NOT include Authorization Pages, Indices, Section General Pages and Appendixes.

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at <http://www.ul.com/global/eng/pages/corporate/contactus>.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above.

This material is provided on behalf of UL LLC(UL) or any authorized licensee of UL.

SUZ File

UL INSPECTION CENTER 749

CERTIFICATE OF COMPLIANCE

Certificate Number 20150114-EX26635
Report Reference EX26635-20141231
Issue Date 2015-JANUARY-14

Issued to: SHANGHAI TOP MOTOR CO LTD
303 KANGLIU RD, KANGQIAO INDUSTRIAL AREA,
NANHUI, SHANGHAI, 201315 CHINA

This is to certify that representative samples of FIRE PUMP MOTORS
T Series, TXD Series, TDC Series, TXA Series, TXD Series: See Addendum Page below for Models

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1004-1, Rotating Electrical Machines - General Requirements; UL 1004-5, Fire Pump Motors

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus



CERTIFICATE OF COMPLIANCE

Certificate Number 20150114-EX26635
Report Reference EX26635-20141231
Issue Date 2015-JANUARY-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.,

T801-2, T802-2, T803-2, T90S-2, T90L1-2, T90L2-2, T100L1-2, T100L2-2, T112M1-2, T112L-2, T132S1-2, T132S2-2, T132M1-2, T132M2-2, T132M3-2, T160M1-2, T160M2-2, T160L1-2, T160L2-2, T180M-2, T180L-2, T200L1-2, T200L2-2, T200L3-2, T225M-2, T225M2-2, T250M1-2, T250M2-2, T280S-2, T280M-2, T280M2-2, T315S-2, T315M-2, T315L1-2, T315L2-2, T355M-2, T355M1-2, T355M2-2, T355L1-2, T355L2-2, T802-4, T803-4, T90S-4, T90L1-4, T90L2-4, T100L1-4, T100L2-4, T100L3-4, T112M-4, T112L-4, T132S-4, T132M-4, T132L1-4, T132L2-4, T160M-4, T160L1-4, , T160L2-4, T180M-4, T180L1-4, T180L2-4, T200L1-4, T200L2-4, T225S-4, T225M-4, T225M2-4, T250M1-4, T250M2-4, T280S-4, T280M-4, T280M2-4, T315S-4, T315M-4, T315L1-4, T315L2-4, T355M1-4, T355M2-4, T355L1-4, T355L2-4, T355L3-4, T803-6, T90S-6, T90L1-6, T90L2-6, T100L1-6, T100L2-6, T112M-6, T112L-6, T132S-6, T132M1-6, T132M2-6, T132L-6, T160M-6, T160L1-6, , T160L2-6, T180L1-6, T180L2-6, T200L1-6, T200L2-6, T200L3-6, T225M1-6, T225M2-6, T250M1-6, T250M2-6, T280S-6, T280M-6, T280M2-6, T315S-6, T315M-6, T315L1-6, T315L2-6, T355M1-6, T355M2-6, T355M3-6, T355L1-6, T355L2-6, TXC143T1U2B, TXC143T1U2B, TXC143T1.5U2B

TXC143T1.5U2B, TXC145T2U2B, TXC145T2U2B, TXC182T3U2B, TXC182T3U2B, TXC184T5U2B, TXC184T5U2B, TXC213T7.5U2B, TXC213T7.5U2B, TXC215T10U2B, TXC215T10U2B, TXC254T15U2B, TXC254T15U2B, TXC256T20U2B, TXC256T20U2B, TXC284TS25U2B, TXC284TS25U2B, TXC286TS30U2B, TXC286TS30U2B, TXC324TS40U2B, TXC324TS40U2B, TXC326TS50U2B, TXC326TS50U2B, TXC364TS60U2B, TXC364TS60U2B, TXC365TS75U2B, TXC365TS75U2B, TXC405TS100U2B, TXC405TS100U2B, TXC444TS125U2B, TXC444TS125U2B, TXC445TS150U2B, TXC445TS150U2B, TXC447TS200U2B, TXC447TS200U2B, TXC449TS250U2B, TXC449TS250U2B, TXC143T1U4B, TXC143T1U4B, TXC145T1.5U4B, TXC145T1.5U4B, TXC145T2U4B, TXC145T2U4B, TXC182T3U4B, TXC182T3U4B, TXC184T5U4B, TXC184T5U4B, TXC213T7.5U4B, TXC213T7.5U4B, TXC215T10U4B, TXC215T10U4B, TXC254T15U4B, TXC254T15U4B, TXC256T20U4B, TXC256T20U4B, TXC284T25U4B, TXC284T25U4B, TXC286T30U4B, TXC286T30U4B, TXC324T40U4B, TXC324T40U4B, TXC326T50U4B, TXC326T50U4B, TXC364T60U4B, TXC364T60U4B, TXC365T75U4B, TXC365T75U4B, TXC405T100U4B, TXC405T100U4B, TXC444T125U4B, TXC444T125U4B, TXC445T150U4B, TXC445T150U4B, TXC447T200U4B, TXC447T200U4B, TXC449T250U4B, TXC449T250U4B, TXC145T1U6B, TXC145T1U6B, TXC182T1.5U6B, TXC182T1.5U6B, TXC184T2U6B, TXC184T2U6B, TXC213T3U6B, TXC213T3U6B, TXC215T5U6B, TXC215T5U6B, TXC254T7.5U6B, TXC254T7.5U6B, TXC256T10U6B, TXC256T10U6B, TXC284T15U6B, TXC284T15U6B, TXC286T20U6B, TXC286T20U6B, TXC324T25U6B, TXC324T25U6B, TXC326T30U6B, TXC326T30U6B, TXC364T40U6B, TXC364T40U6B, TXC365T50U6B, TXC365T50U6B, TXC404T60U6B, TXC404T60U6B, TXC405T75U6B, TXC405T75U6B, TXC444T100U6B, TXC444T100U6B, TXC445T125U6B, TXC445T125U6B, TXC447T150U6B, TXC447T150U6B, TXC449T200U6B, TXC449T200U6B

B. Mahrenholz

Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus



CERTIFICATE OF COMPLIANCE

Certificate Number 20150114-EX26635
Report Reference EX26635-20141231
Issue Date 2015-JANUARY-14

TDC254T15U2B, TDC254T15U2B, TDC256T20U2B, TDC256T20U2B, TDC284TS25U2B, TDC284TS25U2B, TDC286TS30U2B, TDC286TS30U2B, TDC324TS40U2B, TDC324TS40U2B, TDC326TS50U2B, TDC326TS50U2B, TDC364TS60U2B, TDC364TS60U2B, TDC365TS75U2B, TDC365TS75U2B, TDC405TS100U2B, TDC405TS100U2B, TDC444TS125U2B, TDC444TS125U2B, TDC445TS150U2B, TDC445TS150U2B, TDC254T15U4B, TDC254T15U4B, TDC256T20U4B, TDC256T20U4B, TDC284T25U4B, TDC284T25U4B, TDC286T30U4B, TDC286T30U4B, TDC324T40U4B, TDC324T40U4B, TDC326T50U4B, TDC326T50U4B, TDC364T60U4B, TDC364T60U4B, TDC365T75U4B, TDC365T75U4B, TDC405T100U4B, TDC405T100U4B, TDC444T125U4B, TDC444T125U4B, TDC445T150U4B, TDC445T150U4B, TDC254T7.5U6B, TDC254T7.5U6B, TDC256T10U6B, TDC256T10U6B, TDC284T15U6B, TDC284T15U6B, TDC286T20U6B, TDC286T20U6B, TDC324T25U6B, TDC324T25U6B, TDC326T30U6B, TDC326T30U6B, TDC364T40U6B, TDC364T40U6B, TDC365T50U6B, TDC365T50U6B, TDC404T60U6B, TDC404T60U6B, TDC405T75U6B, TDC405T75U6B, TDC444T100U6B, TDC444T100U6B, TDC445T125U6B, TDC445T125U6B

TXA143T1U2B, TXA143T1U2B, TXA143T1.5U2B, TXA143T1.5U2B, TXA145T2U2B, TXA145T2U2B, TXA182T3U2B, TXA182T3U2B, TXA184T5U2B, TXA184T5U2B, TXA213T7.5U2B, TXA213T7.5U2B, TXA215T10U2B, TXA215T10U2B, TXA215T15U2B, TXA215T15U2B, TXA143T1U4B, TXA143T1U4B, TXA145T1.5U4B, TXA145T1.5U4B, TXA145T2U4B, TXA145T2U4B, TXA182T3U4B, TXA182T3U4B, TXA184T5U4B, TXA184T5U4B, TXA213T7.5U4B, TXA213T7.5U4B, TXA215T10U4B, TXA215T10U4B, TXA145T1U6B, TXA145T1U6B, TXA182T1.5U6B, TXA182T1.5U6B, TXA184T2U6B, TXA184T2U6B, TXA213T3U6B, TXA213T3U6B, TXA215T5U6B, TXA215T5U6B

TXD48 1/4U2B, TXD48 1/4U2B, TXD48 1/3U2B, TXD48 1/3U2B, TXD48 1/2U2B, TXD48 1/2U2B, TXD48 3/4U2B, TXD48 3/4U2B, TXD56 1/4U2B, TXD56 1/4U2B, TXD56 1/3U2B, TXD56 1/3U2B, TXD56 1/2U2B, TXD56 1/2U2B, TXD56 3/4U2B, TXD56 3/4U2B, TXD56H 1U2B, TXD56H 1U2B, TXD56H 1.5U2B, TXD56H 1.5U2B, TXD56H 2U2B, TXD56H 2U2B, TXD56H 3U2B, TXD56H 3U2B, TXD143T 1U2B, TXD143T 1U2B, TXD143T 1.5U2B, TXD143T 1.5U2B, TXD145T 2U2B, TXD145T 2U2B, TXD145T 3U2B, TXD145T 3U2B, TXD182T 5U2B, TXD182T 5U2B, TXD184T 7.5U2B, TXD184T 7.5U2B, TXD213T 10U2B, TXD213T 10U2B, TXD215T 15U2B, TXD215T 15U2B, , TXD48 1/4U4B, TXD48 1/4U4B, TXD48 1/3U4B, TXD48 1/3U4B, TXD48 1/2U4B, TXD48 1/2U4B, TXD48 3/4U4B, TXD48 3/4U4B, TXD56 1/4U4B, TXD56 1/4U4B, TXD56 1/3U4B, TXD56 1/3U4B, TXD56 1/2U4B, TXD56 1/2U4B, TXD56 3/4U4B, TXD56 3/4U4B, TXD56H 1U4B, TXD56H 1U4B, TXD56H 1.5U4B, TXD56H 1.5U4B, TXD56H 2U4B, TXD56H 2U4B, TXD143T 1U4B, TXD143T 1U4B, TXD145T 1.5U4B, TXD145T 1.5U4B, TXD145T 2U4B, TXD145T 2U4B, TXD182T 3U4B, TXD182T 3U4B, TXD184T 5U4B, TXD184T 5U4B, TXD213T 7.5U4B, TXD213T 7.5U4B, TXD215T 10U4B, TXD215T 10U4B, TXD56 1/4U6B, TXD56 1/4U6B, TXD56 1/3U6B, TXD56 1/3U6B, TXD56 1/2U6B, TXD56 1/2U6B, TXD56 3/4U6B, TXD56 3/4U6B, TXD56H 1U6B, TXD56H 1U6B, TXD145T 1U6B, TXD145T 1U6B, TXD182T 1.5U6B, TXD182T 1.5U6B, TXD184T 2U6B, TXD184T 2U6B, TXD213T 3U6B, TXD213T 3U6B, TXD215T 5U6B, TXD215T 5U6B ,

B. Mahrenholz

Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus

